Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
					Check	Yes / No		Submitted		<ul><li>2 Tooling</li><li>3 Setup</li></ul>			
		Notes	Inspector		Mtrl	Approved	Time Of Day	Date Part	ınce				
			Inspection Record	First Part Ir					Down Time Codes	Down Ti	ctions	Special Notes / Instructions	Specia
													ROUTING:
	9												
	2												
		1	19										
		S	ころ						1				
					1								
		5											
		S							1				
										(J		88	12/21
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					lime		Hrs.				
		Thru-		Pcs./Hr			Cycle	3	Setup			Mach. No.	
									oility.	Do not require traceability.	Do not req	Caps/Plugs	Caps
					1		i a	Located on the bag followed by "Lot Number."	lowed by "	the bag fol	Located on	Snap Rings	Snap
					I		box label.	Use their work order number and date on the box label.	umber and	ork order n	Use their w	Flare Tubes	Flare
		63					etter "M."	Located on the spool label, starting with the letter "M."	abel, starti	the spool l	Located on	Copper Tubing	Coppe
							vord "heat."	Located on the box label, directly above the word "heat."	el, directly	the box lab	Located on	Brazing Rings	Brazir
							ox quantity.	Six digit no. located on the box label under box quantity.	the box la	. located on	Six digit no	Flare Nuts	Flar
		20151504	G-RING					mbers	eablity Nu	Distinguishing Traceablity Numbers	Disting		
		N/A	G10							ω		Order Qty	Ord
	į	No(s)	component(s)	Con		LLC	devices, LLC	4		392260	3:	Order No.	Ord
	lity	Heat Lot/Traceability		,			7			G10-R	0	Part No.	Pai