Test Form 11/4/15	Test F									2	BRAZING PRODUCTION RECORD	DRALING PRO
									Meeting	6		
									Training			
									Setup			
	S	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling			
		ALCOHOLD STATE	First Part Inspection Record	First Part I					Down Time Codes		Special Notes / Instructions	Specia
												ROUTING:
	Þ											
	1						-					
		2 01										
)	St.										
	E											
	2						1					
				-								
9									Ĩ.		GS	zz/h
Scrap	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					IIme		Піз			
		Thru-		Pcs./Hr			Cycle	ō	Setup		Mach. No.	
									traceability.	Do not require traceability.	Caps/Flugs	Cap
					1		• =	"Lot Number	Located on the bag followed by "Lot Number."	ocated on the		Snap
							e box label.	nd date on the	Use their work order number and date on the box label.	Jse their work		Flare
							letter "M."	ing with the I	Located on the spool label, starting with the letter "M."	ocated on the	σq	Coppe
					L	-	word "heat."	ly above the v	Located on the box label, directly above the word "heat."	ocated on the	Brazing Rings	Brazir
							ox quantity.	abel under bo	Six digit no. located on the box label under box quantity.	six digit no. loc	Flare Nuts	Flar
		N/A	C-RING					umbers	Distinguishing Traceablity Numbers	Distinguish		
	01	343295	1102-16-1/4	13				1		14	Order Qty	Ord
		No(s)	Component(s)	60		LLC	devices, LLC	T T	12	397792	Order No.	Ord
	bility	Heat Lot/Traceability		,			1		1/4-R	1102-16-1/4-R	Part No.	Pai