Test Form 11/4/15	Test Fo.										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
	72.									5 Training			
			2										
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	ice	<ol> <li>Maintenance</li> <li>Tooling</li> </ol>			
			t Inspection Record	First Part Ir		The little		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ne Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	7												
58 													
			(										
		)	5										
			100										
			· XX										
			- 11 (										
													-
							Ø	7		7	25min	JTU	1/8/1
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cu	Total Pcs.	Prod Hrs.	Emp. Name	Date
		back out			A APPLICATION		THILLIC						
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
									lity.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
					<u> </u>			Located on the bag followed by "Lot Number."	owed by "I	the bag follo	Located on		Snap
							box label.	Use their work order number and date on the box label.	ımber and	ork order nu	Use their w	Flare Tubes	Flare
					1		etter "M."	Located on the spool label, starting with the letter "M."	bel, startir	the spool la	Located on	Copper Tubing	Coppe
			CP13				ord "heat."	Located on the box label, directly above the word "heat."	el, directly	the box lab	Located on	Brazing Rings	Brazir
			BRZ03		I		x quantity.	Six digit no. located on the box label under box quantity.	the box la	located on	Six digit no.	Flare Nuts	Flan
			CUTU-1-1/2	CU				mbers	ablity Nur	Distinguishing Traceablity Numbers	Distingu		
		396370	SF404-4-5/16	SF4	l					6		Order Qty	Ord
		No(s)	component(s)	Con		LLC	devices, LLC	4		396370	39	Order No.	Ord
	ity	Heat Lot/Traceability					2			S404-4-5/16	S404	Part No.	Par