Test Form 11/4/15	Test Fo			ਟ)RD	BRAZING PRODUCTION RECORD	BRAZING PRO
									Meeting			
									FAIR Training	5 2		
			N						Setup	ω		
	35	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2 1		
			Inspection Record	First Part I					Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
	5											
	2											
		(1									
		55										
	0						Ø	7	9	35 min	770	1/14/10
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date /
1		but/onis					111110					
		Thru-		Pcs./Hr			Cycle	" ชั	Setup		Mach. No.	
					-				e traceability.	Do not require traceability.	Caps/Plugs	Caps
							=	"Lot Number.	Located on the bag followed by "Lot Number."	ocated on th		Snap
							box label.	nd date on the	Use their work order number and date on the box label.	Jse their worl	Flare Tubes	Flare
							etter "M."	ting with the I	Located on the spool label, starting with the letter "M."	ocated on th	Copper Tubing	Coppe
			CP13			255	vord "heat."	ly above the v	Located on the box label, directly above the word "heat."	ocated on th	Brazing Rings	Brazir
			CUTU-1-1/2	כנ			x quantity.	label under bo	Six digit no. located on the box label under box quantity.	six digit no. lo	Flare Nuts	Flare
			BRZ03					umbers	Distinguishing Traceablity Numbers	Distinguish		
		39694	SF405-2-1/4-1/2	SF40						12	Order Qty	Orde
		No(s)	Component(s)	6		LLC	devices, LLC	H	41	396941	Order No.	Ord
	bility	Heat Lot/Traceability					227	J	/4-1/2	S405-2-1/4-1/2	Part No.	Par