Part No.	1301-	1301-22-1/4-R		9	control			Com	nonent(s)	Heat Lot/	Heat Lot/Traceability		nere a secon
Order No.	35	397713		T.	devices, LLC	.LC		COII	component(s)	7	No(s)		
Order Qty		50						130	1301-22-1/4	397	560	_	
	Disting	Distinguishing Traceablity Numbers	ity Numb	ers				,	A-RING	0-	1300		-
Flare Nuts	Six digit no	Six digit no. located on the box label under box quantity.	box label	l under bo	ox quantity.								
Brazing Rings	Located on	Located on the box label, directly above the word "heat."	lirectly ab	ove the v	vord "heat."								
Copper Tubing	Located on	Located on the spool label, starting with the letter "M."	, starting	with the l	etter "M."								
Flare Tubes	Use their w	Use their work order number and date on the box label.	er and da	ate on the	e box label.								
Snap Rings	Located on	Located on the bag followed by "Lot Number."	ed by "Lot	Number	. "								
Caps/Plugs	Do not requ	Do not require traceability.											
					And the little								
Mach. No.	: 40		Setup Hrs.		Cycle Time			Pcs./Hr		Thru- put/8hrs			
Date Emp. Name	Prod Hrs.	Total Pcs.	Cum. Total	Total	Down Time	Down Time Code			Notes		Sc	Scrap	Scrap Code
95 17/1		50											
												1	
											É		
0.00										5	1		
										10	52		
											*		
ROUTING:													
Special Notes / Instr	/ Instructions	Down Time (Codes					First Part In	First Part Inspection Record				
				Date Part	1 0 0 0	Approved	Mtrl	Don't ottor	5		201		
				Submitted	Time Of Day	Yes / No	20000	Rev Letter	Inspector		Notes		
		6 Meeting											
BRAZING PRODUCTION RECORD	CORD											Test For	Test Form 11/4/15