								BRAZING PRODUCTION RECORD	BBAZING BR
			$\vdash$			Setup FAIR Training	ω 4 τ		
	r Inspector	Rev Lett	Approved Mtrl Yes / No Check	Time Of Day Al	Date Part Submitted		2 1		
	rt Inspection Record	First Part				Down Time Codes	tions	Special Notes / Instructions	Specia
					31				ROUTING:
	,		1				8.		
25	,								
35									
							1		
						-1		Ö	517.0
			Code					3	3/0
	Notes		Down Time	Down Time D	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
Thru- put/8hrs	,	Pcs./Hr		Cycle Time	s, nb	Setup Hrs.		Mach. No.	
		4				Do not require traceability.	Do not requi	Caps/Plugs	Caps
				. "	y "Lot Number.	Located on the bag followed by "Lot Number."	ocated on t		Snap
				box label.	and date on the	Use their work order number and date on the box label.	Jse their wo	Flare Tubes	Flare
				etter "M."	rting with the l	Located on the spool label, starting with the letter "M."	ocated on t	Copper Tubing	Coppe
				vord "heat."	tly above the w	Located on the box label, directly above the word "heat."	ocated on t	Brazing Rings	Brazii
20060667	E-RING			ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no. I	Flare Nuts	Flar
N/A	E10				Numbers	Distinguishing Traceablity Numbers	Distingui		
39026	901-15-3/16	9				4		Order Qty	Ord
No(s)	Component(s)		Ö	devices, LLC	T C	401302	401	Order No.	Ord
Heat Lot/Traceability						901-15-3/16-10	901-15-	Part No.	Pai