Order No.	392176		10	control	5	4	Component(s)	Heat Lot/1	Heat Lot/Traceability	
Order Qty	30					丁	SF403-5-3/16	30,5	74162	
	Distinguishing Traceablity Numbers	raceablity Num	bers			\neg	BRZ03	•		
Flare Nuts Six	Six digit no. located on the box label under box quantity.	on the box lab	el under bo	quantity.			CFT-1/2			
Brazing Rings Lo	Located on the box label, directly above the word "heat."	label, directly	above the w	ord "heat."			FLR-1/2			
04	Located on the spool label, starting with the letter "M."	ol label, startin	g with the le	tter "M."						
	Use their work order number and date on the box label	er number and	date on the	box label.						
,	Located on the bag followed by "Lot Number."	followed by "L	ot Number."							
1	Do not require traceability.	eability.								
AND THE RESIDENCE OF THE CASE		THE PERSON NAMED IN			Michigan Schools					M
Mach. No.		Setup Hrs.	Q	Cycle Time		Pcs./	/нг	Thru- put/8hrs		and the S
Date Care	Brod Hrs. Total Box	A Value	Cim Total	H	Down Time		Notes			
	-				Code)		H
1/15 STU 1	Compos 3		Ť	Ø	41	Raw 31	Complexe	Their		-
) (h		
							5	, - , -		+
								S		-
									?	
ROUTING:	-	-							Č	-
Special Notes / Instructions		Down Time Codes				First	First Part Inspection Record	rd		
30	 Mainter Tooling 	Maintenance Tooling	Date Part Submitted	Time Of Day	Approved Yes / No	Mtrl Check Rev L	Rev Letter Inspector	28	Notes	
	3 Setup 4 FAIR		51-4-12	102	-	0	AF	\$ 500 M		
	5 Training 6 Meeting	ng				1				