			1 I									
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	e	 Maintenance Tooling Setup 			
		First Part Inspection Record	First Part Ir					e Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
				I								
		1										
		1/1										
	-											
+								-				
											SB	3/19
ap Scrap	Scrap	Notes			Down Time Code	Down Time	Cum. Total	C	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs					Time		Hrs.				
	Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
								ity.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
						` =	Lot Number.	wed by "	Located on the bag followed by "Lot Number."	ocated on		Snap
						box label.	date on the	mber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						etter "M."	ng with the l	oel, startin	Located on the spool label, starting with the letter "M."	ocated on	Copper Tubing	Coppe
				I		vord "heat."	above the w	l, directly	Located on the box label, directly above the word "heat."	ocated on	Brazing Rings	Brazir
	N/A	A-KF004	1			ox quantity.	bel under bo	he box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
	NA	DCN316-HT	DC				mbers	ablity Nur	Distinguishing Traceablity Numbers	Distingu		
	177004	2203A-10-3/16-0	2203.	l				Ш	1		Order Qty	Ord
	No(s)	Component(s)	Con		LLC	devices, LLC	C C		401300	40	Order No.	Ord
	Heat Lot/Traceability					OD TOO	J					1 01