			The second secon								
							04 04	5 Training6 Meeting			·¥
Notes	Inspector	Rev Letter	Check	Approved Yes / No	Time Of Day	Date Part Submitted	nance	 Maintenance Tooling 			
	First Part Inspection Record	First Part					Down Time Codes	Down	ctions	Special Notes / Instructions	Specia
											ROUTING:
	51	_									
	100	=									
	12/1										
	2									1	
							+				
<mark>-</mark> ار	ON SHELF	YARTS C	7		B			S)	1/2 HRS	THE STATE OF THE S	4/12
	Notes)	Down Time Code	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
put/onis			No. of the last		lime		ms.				
Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
							ability.	uire tracea	Do not require traceability.	Caps/Plugs	Caps
	1				-	ot Number.	Located on the bag followed by "Lot Number."	the bag fo	Located on	Snap Rings	Snap
	3				box label.	date on the	Use their work order number and date on the box label.	ork order	Use their w	Flare Tubes	Flare
					etter "M."	ng with the le	Located on the spool label, starting with the letter "M."	the spool	Located on	Copper Tubing	Coppe
					ord "heat."	above the w	Located on the box label, directly above the word "heat."	the box la	Located on	Brazing Rings	Brazin
	BRZ00		L		x quantity.	pel under bo	Six digit no. located on the box label under box quantity.	. located o	Six digit no.	Flare Nuts	Flare
۰-۰	CASC-11	,				nbers	Distinguishing Traceablity Numbers	uishing Tra	Distingu		
•-)	ASC-11		Ĺ					21		Order Qty	Orde
No(s)	Component(s)	-		LC.	devices, LLC	H		390240	39	Order No.	Orde
Heat Lot/ Iraceability	mnonon+/cl	3			2010			700 11	2		rait No.