										6 Meeting			
	\$	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted		 Maintenance Tooling 			
			First Part Inspection Record	First Part I					Codes	Down Time	ctions	Special Notes / Instructions	Specia
													ROUTING:
	8												
	2					6							
		5,7											
		F . C .								10 mm			
		7.1											
										7		88	1/26
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cun	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8nrs					lime		Hrs.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
				(*)					×	Do not require traceability.	Do not requ	Caps/Plugs	Caps
								ot Number.	ed by "Lo	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
							box label.	date on the	ber and	Use their work order number and date on the box label	Use their w	Flare Tubes	Flare
							etter "M."	g with the le	l, starting	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
							ord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
							x quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flan
	1-6-	NIA	C-RING					bers	olity Num	Distinguishing Traceablity Numbers	Distingu		
		393779	1101-9-5/16	11				ı		7		Order Qty	Orde
		No(s)	omponent(s)	COI		TC	devices, LLC	4		398162	39	Order No.	Ord
	ility	Heat Lot/Traceability	nonent(s)	C C			ontrol			1101-9-5/16-R	1101-9	Part No.	Par