										Meeting	6		
								A THURST			UI J		
	inorco		All of the second		Check	Yes/No	10:20	Submitted		Tooling Setup	A 33 12		
	Notes	4	Inspector	Rev Letter	$\dashv$	Approved	Time Of Day	Date Part		Maintenance			
			Inspection Record	First Part Ir				The second	Codes	Down Time	tions	Special Notes / Instructions	Special
													ROUTING:
	Z												
	?			3									
		Ó			1								
		00	33	1									
		5											
					T								
										2	15 min	CS	12/1/15
Scrap Code	Scrap		Notes ·		В	Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
The same of		put/8nrs					IIme		nrs.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
					_				Y.	Do not require traceability.	Do not requ		Caps/Plugs
							î=	ot Number	ed by "L	Located on the bag followed by "Lot Number."	Located on t	Rings	Snap Rings
			CP14				box label.	date on the	ber and	Use their work order number and date on the box label.	Use their wo	Tubes	Flare Tubes
	173	133	BRZ07				etter "M."	g with the I	l, startin	Located on the spool label, starting with the letter "M."	Located on t	Tubing	Copper Tubing
	1474	W 8 W	CSW-3-5/8	S			vord "heat.'	above the v	directly a	Located on the box label, directly above the word "heat."	Located on t	Rings	<b>Brazing Rings</b>
		\	BRZ22				ox quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
	5650	.8M	CUTU-36-5/32	CUI				bers	olity Num	Distinguishing Traceablity Numbers	Distingui		
	583	160	SF5-2.5-16	IS.						2		Qty	Order Qty
	No(s)	2	Component(s)	Con		LLC	devices, LLC	A		391583	39:	r No.	Order No.
	Heat Lot/Traceability	Heat Lot/					201			35-2.5-16-36-B	33-2.3	INO.	Part No.