Test Form 11/4/15	Te										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
	Notes		Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted		2 Tooling 3 Setup			
					Mtr	Approved		Date Part	ro				
			† Inspection Record	First Part In					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	7												
	>												
		J	0			1							
		200										1	
	•												
	5												
										1			
										೩೦		38	3/35
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Сп	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs				8	IIme		nis.	Sale Palestrania Sales	State Could Apple		
		Thru-		Pcs./Hr			Cycle	.2	Setup			Mach. No.	
									ity.	Do not require traceability.	Do not req	Caps/Plugs	Cap
							=	Lot Number.	wed by "I	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
					<u> </u>		box label.	date on the	mber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
							etter "M."	ng with the l	el, startir	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
				_		-	vord "heat."	above the w	l, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
							οχ quantity.	bel under bo	he box lai	Six digit no. located on the box label under box quantity.	Six digit no	Flare Nuts	Flar
	0667	30060667	E-RING					nbers	ablity Nur	Distinguishing Traceablity Numbers	Disting		
	63	C9510H	901-10-1/4	90						20		Order Qty	Ord
	No(s)	N	Component(s)	Cor		LLC	devices, LLC	H		401862	4(Order No.	Orc
	Heat Lot/Traceability	Heat Lot/	T. A.	,			1	ı		901-10-1/4-R	901-	Part No.	Pa