											Company Compan	1	1
				1				1		5 Meeting	6		
		(94 insp)	XX	124	•	ah	14	N/KI			ω 4 τ		
	S	Notes	Inspector	Rev Letter	d Mtrl	Approved Yes / No	Time Of Day	Date Part Submitted		 Maintenance Tooling 	1 2		
			First Part Inspection Record	First Part In					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	9				\parallel								
)	B											
		100				4					ñ		
					+								
					+								
		×	44										
					+	(1		_	11	-	CD	5
Code					+	COUL			5	Š		ō	5
Scrap	Scrap		Notes		ō	Down Time	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
		Thru- put/8hrs	more than	Pcs./Hr	+	fast	Cycle Time	\	Setup Hrs.		2	Mach. No.	
T.										TOTAL STREET,			
									1.	Do not require traceability.	Do not requi		Caps
							[:=]	t Number.	ed by "Lo	Located on the bag followed by "Lot Number."	ocated on t		Snap
							box label.	late on the	ber and o	Use their work order number and date on the box label.	Jse their wo		Flare
							etter "M."	with the le	, starting	Located on the spool label, starting with the letter "M."	ocated on t	-	Coppe
	11111)	CP13	26		*	ord "heat."	bove the w	directly a	Located on the box label, directly above the word "heat."	ocated on t	Brazing Rings	Brazin
		D50988	BRZ03				x quantity.	el under bo	box lab€	Six digit no. located on the box label under box quantity.	Six digit no. I	Flare Nuts	Flare
		M85650	CUTU0-1/2	2				bers	lity Numl	Distinguishing Traceablity Numbers	Distingui		
		KIN	SF403-6-3/16	SF4	į					12	1	Order Qty	Orde
	48.7	No(s)	component(s)			LLC	devices, LLC	THE COLUMN	8	390831	390	Order No.	Orde
	ility	Heat Lot/Traceability	popon+(c)				ontrol			S403-6-3/16	S403-	Part No.	Par

Ü