									н			
				1000	Local States	Service and	Section States		6 Meeting			
		q	(,			STATE OF THE PARTY				
		THE STATE OF THE S)	7		6:25	3.2216					
	Notes	Inspector	Rev Letter	Mtrl	Approved Yes / No	Time Of Day	Date Part Submitted	è	 Maintenance Tooling 			
		First Part Inspection Record	First Part In				S. Comments	e Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
	Art Co		Market Inches			The last Contract						ROUTING:
Ċ		1										
Q												
	9											
	5.	2.6										
	3	ٽ										
						4		6	0	J MIC	L	71001
						Ì	N		1	16	1	2/20/11
Scrap Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
	but our							111.5				
	Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
								ту.	Do not require traceability.	Do not requ	Caps/Plugs	Caps/
						=	ot Number.	wed by "Lo	Located on the bag followed by "Lot Number."	Located on		Snap
						box label.	date on the	nber and c	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
				1		etter "M."	with the le	el, starting	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Copper
		CP13				ord "heat."	bove the w	, directly a	Located on the box label, directly above the word "heat."	Located on		Brazing Rings
		BRZ23		L		x quantity.	el under bo	ne box labo	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
		CUTU-1-1/2	CU				bers	blity Num	Distinguishing Traceablity Numbers	Distingu		
		SF403-6-3/16	SF4	<u>U</u>					15	200 1 2 2 4	r Qty	Order Qty
	No(s)	component(s)	COL		LC	devices, LLC	7		404022	40	r No.	Order No.
ity	Heat Lot/Traceability	5000+(c)	2			ontrol			S403-6-3/16	S403	No.	Part No.