			ß				Meeting	6		
								υдп		
	Notes	Inspector	Mtrl Rev Letter	Approved N Yes / No Ch	Time Of Day	Date Part Submitted		2 2 1		
		First Part Inspection Record	First Part I			5	Down Time Codes	ctions	Special Notes / Instructions	Speci
										ROUTING:
(a)										
							300		SB	1/2,
Scrap Code		Notes		Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
Scra		of Parameter and San		The last						
	Thru- put/8hrs		Pcs./Hr		Cycle Time	s. d	Setup Hrs.		Mach. No.	
							Do not require traceability.	Do not requi	Caps/Plugs	Cap
					=	y "Lot Number.	Located on the bag followed by "Lot Number."	ocated on t		Snaj
					box label.	ind date on the	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
					etter "M."	rting with the l	Located on the spool label, starting with the letter "M."	ocated on t	Copper Tubing	Coppe
<u> </u>					ord "heat."	tly above the w	Located on the box label, directly above the word "heat."	ocated on t	Brazing Rings	Brazi
					ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no. I	Flare Nuts	Flar
	20140766	J-RING				lumbers	Distinguishing Traceablity Numbers	Distinguis		
	392996	501-3-1/4	ъ	E)			200	2(Order Qty	Ord
	No(s)	component(s)	6	С	devices, LLC	Ti M	392851	392	Order No.	Ord
_	Heat Lot/Traceability	anonont(c)	2		OP TOO	ı	5U1-3-1/4-K	5-TOC	Part No.	Pai