									ting	6 Meeting			
				1					7				
	es	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling Setun	<ol> <li>Mainter</li> <li>Tooling</li> <li>Setup</li> </ol>			
			First Part Inspection Record	First Part In					Down Time Codes		ctions	Special Notes / Instructions	Special
													ROUTING:
	Þ												
		, ,	5										
		5	7										
		14	5										
		110											
								18.					
									Q	115		SG	2/1
Scrap	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs. Cu	12	Prod Hrs.	Emp. Name	Date
		put/8hrs		1,000			Time		Hrs.				
		Thru-		Pcs./Hr			Cycle	-0	Setup			Mach. No.	
									ceability.	Do not require traceability.	Do not re	Caps/Plugs	Caps
								"Lot Number.	Located on the bag followed by "Lot Number."	on the ba	Located	Snap Rings	Snap
			_				e box label.	d date on the	Use their work order number and date on the box label.	work orc	Use their	Flare Tubes	Flare
							etter "M."	ing with the I	Located on the spool label, starting with the letter "M."	on the sp	Located	Copper Tubing	Coppe
	6	801108					word "heat."	y above the v	Located on the box label, directly above the word "heat."	on the bo	Located o	Brazing Rings	Brazir
		DAIL OF THE PARTY	J-RING				ox quantity.	abel under bo	Six digit no. located on the box label under box quantity.	no. locate	Six digit ı	Flare Nuts	Flan
		2/4	J4					ımbers	Distinguishing Traceablity Numbers	nguishing	Distir		
		298297	502-9-3/16	5						115		Order Qty	Ord
	ability .	No(s)	Component(s)	Cor		ררכ	devices, LLC	A		398933		Order No.	Ord
	ability	Heat Lot/Traceahility	N N	38					-4	502-9-3/16-4	50	Part NO.	Pdi