Test Form 11/4/15	Test Fo										ORD	BRAZING PRODUCTION RECORD	BRAZING PRO
									ng Ng				
							•		Jg.	4 FAIR 5 Training			
			40	tt	(	~	3	39-16		3 Setup			
	Notes	No	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling				
			Inspection Record	First Part Ir					Down Time Codes	Down	ctions	Special Notes / Instructions	Specia
	ĺ												ROUTING:
	2												
	2												
		•											
		じり											
		クング											
		274											
	2	111											
													, , ,
							B	5		5	Swa		36/16
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/snrs					lime		піз.				
		Thru-		Pcs./Hr			Cycle	=	Setup			Mach. No.	
									eability.	quire trace	Do not require traceability.	Caps/Plugs	Caps
osiju su					•			Lot Number.	Located on the bag followed by "Lot Number."	n the bag	Located or	Snap Rings	Snap
					•		box label.	date on the	Use their work order number and date on the box label.	vork orde	Use their v	Flare Tubes	Flare
					•		etter "M."	ng with the le	Located on the spool label, starting with the letter "M."	າ the spoc	Located or	Copper Tubing	Coppe
11-2-			BRZ23				ord "heat."	above the w	_ocated on the box label, directly above the word "heat."	າ the box	Located or	Brazing Rings	Brazir
			CFT-1/2				x quantity.	bel under bo	Six digit no. located on the box label under box quantity.	). located	Six digit no	Flare Nuts	Flare
-			FLR-1/2					nbers	Distinguishing Traceablity Numbers	uishing Tr	Disting		
			F404-9-3/16	SF4						120		Order Qty	Orde
		No(s)	Component(s)	Con		TC	devices, LLC			402915	4	Order No.	Orde
	ability	Heat Lot/Traceability					2			F404-9-3/16	F40.	Part No.	Par