Test Form 11/4/15	Test Fo)RD	BRAZING PRODUCTION RECORD	BRAZING PR
										1 Married 1909 19			
										3 Setup 4 FAIR			
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	če				
			t Inspection Record	First Part In					e Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
													ROUTING:
	7												
				1									
		K								55			
		30								10			
		11											
		11 0											
					L						-		
										ىۋ		350	1/22
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Сr 	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs		Pcs./Hr			Time		Hrs.			IVIACII. INO.	
		Thru-	The state of the s	Pos /Hz			Cycle		Setup			Mach No	
									lity.	Do not require traceability.	Do not requ	Caps/Plugs	Cap
							=	Lot Number.	wed by "	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
				W.			box label.	date on the	mber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
							etter "M."	ng with the I	pel, starti	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						1	vord "heat."	above the w	ا, directl	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
		NIA	G-RING				ox quantity.	bel under bo	he box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		N/A	GR6		_			mbers	ablity Nu	Distinguishing Traceablity Numbers	Distingu		
		397837	703-4-5/16-1/2	703-						2		Order Qty	Ord
		No(s)	Component(s)	Con		ררכ	devices, LLC	H		397796	35	Order No.	Orc
	i i v	Heat Lot/Traceability								703-4-5/16-1/26	703-4-	Part No.	Pa