Test Form 11/4/15	7									ORD	BRAZING PRODUCTION RECORD	BRAZING PR
									6 Meeting			
				-								
	Notes	er Inspector	Rev Letter	d Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted		 Maintenance Tooling 			
		t Inspection Record	First Part					Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
												ROUTING:
	1											
5.												
	1/2	Y										
	7,5	7										
	1 //											
			Ď									
									9		SB	4/10
Scrap Code	Scrap	Notes		ō	Down Time Code	Down Time	Cum. Total	Cui	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hi			Cycle Time		Setup Hrs.			Mach. No.	
			No. of Concession, Name of Street, or other Persons of Concession, Name of Street, or other Persons of Concession, Name of Street, or other Persons of Concession, Name of Street, One of	muderal order	CONTRACTOR OF THE PARTY OF THE			September 1			See all the second second second	
								Ý.	Do not require traceability.	Do not requ	Caps/Plugs I	Caps
				<u> </u>		. =	ot Number.	red by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
	7.7					box label.	date on the	ber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						etter "M."	ng with the I	યે, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						vord "heat.'	above the v	directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
	N/A	A-KF004				ox quantity.	oel under bo	e box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flan
	ZIA	DNC316-HT					nbers	olity Nun	Distinguishing Traceablity Numbers	Distingu		
	398745	2203A-2-1/4-0	22						6		Order Qty	Ord
	No(s)	Component(s)	5		LLC	devices, LLC			399531	39	Order No.	Ord
	Heat Lot/Traceability		,			ontrol			2203A-2-1/4	2203	Part No.	Par