								6 Weeting			
	00 (00) 00)	THE STATE OF THE S	7		Jam	11-9-15					
Notes		Rev Letter Inspection Record	Mtrl Rev Letter	Approved Yes / No	Time Of Day	Date Part Submitted	Down Time Codes Maintenance Tooling		ctions	Special Notes / Instructions	Specia
Ш											ROUTING:
1							-				
				-							
1		ı	ÿ.								
1	-			- H							
1	A										
										14	
- 1						30 MIN.	(s)	W	10 Min	E	11/9/15
		Notes		Down Time Code	Down Time	Cum. Total	C	Total Pcs.	Prod Hrs.	Emp. Name	Date
B:	put/8hrs	*	Pcs./Hr		Cycle Time	. 5	Setup Hrs.			Mach. No.	
35-									THE REPORT OF	ALC: NO SHAPE THE PARTY OF	
							ility.	Do not require traceability.	Do not requ		Caps,
1					-	Located on the bag followed by "Lot Number."	owed by '	the bag foll	ocated on	Snap Rings	Snap
		CP15			box label.	Use their work order number and date on the box label	umber and	ork order nu	Jse their wo	Flare Tubes	Flare
1		BRZ09			tter "M."	Located on the spool label, starting with the letter "M."	bel, starti	the spool la	ocated on	Copper Tubing	Copper
		BRZ05			ord "heat."	Located on the box label, directly above the word "heat."	el, directly	the box lab	ocated on	Brazing Rings	Brazin
		CUTU-0-1/4	CUT		x quantity.	Six digit no. located on the box label under box quantity.	the box la	located on	ix digit no.	Flare Nuts	Flare
1		CUTU-0-7/8	CUT			mbers	eablity Nu	Distinguishing Traceablity Numbers	Distingu		
1		1-4-	#					3		r Qty	Order Qty
~	No(s)			C	devices, LLC	d		389767	389	r No.	Order No.
, g	חפמר בטר/ וומכפמטווויץ	omponent(s)	Com		ontrol			S7-4-12-24-C	S7-4-2	No.	Part No.