									6 Meeting			
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Ö	 Maintenance Tooling Setup 			
		t Inspection Record	First Part I					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
	1	4										
	5.1	30										
	200											
		35										
									Se		38	3/29
ap Scrap	Scrap	Notes			Down Time Code	Down Time	Cum. Total	Cur	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs		Pcs./Hr			Time		Hrs.			Mach. No.	
							The state of the s	Cotina			THE REAL PROPERTY.	
				-				ity.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
						=	ot Number.	wed by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
				.		box label.	date on the	mber and	Use their work order number and date on the box label	Use their w	Flare Tubes	Flare
						etter "M."	g with the l	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						ord "heat."	above the w	l, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
						x quantity.	oel under bo	he box lak	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flan
	20060667	E-RING					nbers	ablity Nun	Distinguishing Traceablity Numbers	Distingu		
	NA	902-17-3/16	90						20		Order Qty	Ord
	No(s)	Component(s)	Cor.		TC	devices, LLC	A		405647	40	Order No.	Ord
	Heat Lot/Traceability		?			The state of	l		902-17-3/16-R	902-1	Part No.	Par