BRAZING PRO				Specia	ROUTING:							1	12/8/15	Date			Cap	Snap	Flare	Coppe	Brazi	Flar		Ord	Ord	Pa
BRAZING PRODUCTION RECORD				Special Notes / Instructions									750	Emp. Name		Mach. No.	Caps/Plugs	Snap Rings	Flare Tubes	Copper Tubing	Brazing Rings	Flare Nuts		Order Qty	Order No.	Part No.
ORD				ictions									4	Prod Hrs.			Do not requ	Located on	Use their w	Located on	Located on	Six digit no	Disting		39	S4-
	 Maintenance Tooling Setup FAIR Training Meeting 			Down Time Codes								1.5	100	Total Pcs. Cum. Total	Setup Hrs.	Do not require traceability.	Located on the bag followed by "Lot Number."	ork order num	the spool labe	the box label,	Six digit no. located on the box label under box quantity.	Distinguishing Traceablity Numbers	100	391594	S4-4-2-14	
													100					Use their work order number and date on the box label.	Located on the spool label, starting with the letter "M."	Located on the box label, directly above the word "heat."	e box labe					
		Date Part Submitted									С	el under b	B													
			Time Of Day											Down Time	Cycle Time			e box label.	etter "M."	vord "heat.'	ox quantity.		devices, LLC		ont no	
			Approved Yes / No									Down Time Code									LLC					
		Mtrl Check				P.										_										
				First Part Ins												Pcs./Hr		-:				CU-	CU		Con	
			Inspector	Inspection Record			1							Notes					CP13	BRZ05	BRZ01	CUTU-14-1/4	CUTU-3-1/2	SF4-4-2	Component(s)	Will Change of Epitheorean
							100	2	, 1					Thru- put/8hrs	Thru-								15%	Heat Lo	Heat Lo	
			Notes					U.															-	17651	No(s)	Heat Lot/Traceability
Test						D								Scrap												ility
Test Form 11/4/15														Scrap												