Test Form 11/4/15	Test)RD	BRAZING PRODUCTION RECORD	BRAZING PR
									Training Meeting	6 5		
									FAIR			
	Notes		Inspector	Rev Letter	Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2 2 1		
			First Part Inspection Record	First Part I					Down Time Codes		Special Notes / Instructions	Specia
												ROUTING:
	ð											
	R											
		j										
		2,0										
			20									
												1
									+			
									35		SB	1/8
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs		100/111			Time	S.	Hrs.		relacii. INC.	
		Thru-		Pos /Hr			Cycle	du	Setup		Mach. No.	
					L				traceability.	Do not require traceability.	Caps/Plugs [Caps
							• =	"Lot Number	Located on the bag followed by "Lot Number."	Located on the	Snap Rings	Snap
							e box label.	nd date on the	Use their work order number and date on the box label.	Use their work		Flare
							etter "M."	ting with the I	Located on the spool label, starting with the letter "M."	Located on the	Copper Tubing	Coppe
						1	word "heat."	tly above the v	Located on the box label, directly above the word "heat."	ocated on the	Brazing Rings	Brazii
							ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no. lo	Flare Nuts	Flar
	766	30140766	J-RING					lumbers	Distinguishing Traceablity Numbers	Distinguish		
	7	AIN	501-3-1/4	5						25	Order Qty	Ord
	No(s)	Z	Component(s)	G		ררכ	devices, LLC	G	52	396352	Order No.	Ord
	Heat Lot/Traceability	Heat Lot/		,			7		/4-R	501-3-1/4-R	Part No.	Pai