Test Form 11/4/15	Test Fo										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
				-						6 Meeting			
				2							15		
		(4	<i>D</i> 1	1	5	467	6.40	21.0-					
	A Charles of the Control of the Cont	(0000)					1	12 11			113		
	Notes	3).	Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted		2 Tooling			
			conspection vector	I HOCK OIL II						П			
			contine Books	Eirct Dart Iv					odes	Down Time Codes	rtions	Special Notes / Instructions	Specia
													ROUTING:
	Z												
		g											
		Ų	_										
			_										
		2											
		}											
		-											
							L						
								>		II.		U	
	7						,	ζ G	1	P. Ch			, ,
	Ì						Ø	+	2	2	(400 30 mm)	けて	1/8/1
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cun	Total Pcs.	Prod Hrs.	Emp. Name	Date
						STATE STATE OF	STANDARDER AND			The second second	· · · · · · · · · · · · · · · · · · ·	SACASA CAR	
	144	Thru- put/8hrs	18	Pcs./Hr	N N	3 MIN	Cycle Time	30 MIN	Setup Hrs.	Н2		Mach. No.	
					١						ACTION COLUMN		
										Do not require traceability.	Do not requ	Caps/Plugs	Caps
							=	ot Number.	ed by "Lo	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
							box label.	date on the	ber and	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
					1		etter "M."	g with the le	l, starting	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
							vord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazir
			BRZ00				x quantity.	el under bo	box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flan
			CASC-11	_				bers	lity Num	Distinguishing Traceablity Numbers	Distingu		
	6239	396	ASC-11							20		Order Qty	Ord
	No(s)	2	component(s)	6		LLC	devices, LLC	1		396239	39	Order No.	Ord
	Heat Lot/Traceability	Heat Lot/	nonon+(c)	2			ontrol			ASC-11-7	ASC	Part No.	Par
				115-									