							Nieering	lo		
			7		,		Training	1. D. C.		
	8 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 -	7	>	H	1345pc	1-15-16	Setup	ν ω		
	Notes	Inspector	Mtrl Check Rev Letter	Approved Mi Yes / No Chi	Time Of Day	Date Part Submitted	Maintenance Tooling	2		
		Inspection Record	First Part I			S	Down Time Codes	ctions	Special Notes / Instructions	Specia
-	7									ROUTING:
X	#									
		1								
	5	10								
	6	.0.								
	E.									
					0	5	C	30 miss	J. T.	1/15/16
Scrap Scrap		Notes		Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs		F 65./ III		Time	Hrs.	-		140	
	Thru-		Dos /Hr		Cycle	Setup	Se		Mach No	
	2						Do not require traceability.	Do not requi	Caps/Plugs	Caps
					. =	oy "Lot Number	Located on the bag followed by "Lot Number."	Located on t	Snap Rings	Snap
					e box label.	and date on the	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flare
					letter "M."	arting with the	Located on the spool label, starting with the letter "M."	Located on t	Copper Tubing	Coppe
		CP15			word "heat."	ctly above the v	Located on the box label, directly above the word "heat."	Located on t	Brazing Rings	Brazir
		BRZ09			ox quantity.	x label under b	Six digit no. located on the box label under box quantity.	Six digit no. I	Flare Nuts	Flan
		CUTU-1-7/8				Numbers	Distinguishing Traceablity Numbers	Distingui		
	397134	SF704-20-3/16	SF				5		Order Qty	Ord
	No(s)	Component(s)	22	LC	devices, LLC	H	397134	397	Order No.	Ord
<u> </u>	Heat Lot/Traceability				1		3/04-20-3/16	3/04-2	Fait No.	Par