									6 Meeting			
	Notes	Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted		2 Tooling			
		t Inspection Record	First Part I			STANCES IN		Codes			Special Notes / Instructions	Specia
												ROUTING:
1	1											
	`											
	1.50											
	5											
	110											
											p)	ı
									9		00	h. /.
Code					Code				ڒ		3	
Scrap Scrap		Notes			Down Time	Down Time	Cum. Total	Cun	Total Pcs.	Prod Hrs.	Emp. Name	Date
4	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
				and the second second					Do not require traceability.	Do not requ	Caps/Plugs	Cap
						=	ot Number.	ed by "L	Located on the bag followed by "Lot Number."	Located on	parame	Snaj
						box label.	date on the	ber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						etter "M."	g with the lo	l, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						ord "heat."	above the w	directly a	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazii
	NIA	A-KF003				x quantity.	el under bo	e box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
	NIA	DCN516-HT	D				bers	lity Num	Distinguishing Traceablity Numbers	Distingu		
	393045	2803-12-3/16-0	280						2		Order Qty	Ord
	No(s)	component(s)	COL		LLC	devices, LLC	7		395656	39	Order No.	Ord
	Heat Lot/Traceability	anonont(c)	?			on tool	ı		2803-12-3/16	2803-	Part No.	Pai