Notes									6 Meeting			
Notes												
Notes												
&		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	й	1 Maintenance 2 Tooling			
*		Inspection Record	First Part Ir					e Codes	Down Time	ctions	Special Notes / Instructions	Special
7												ROUTING:
		,										
	is				3							
	11					_						
	5	<u> </u>										
:											(5)	21-01-15
Scrap Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cu	Total Pcs.	Prod Hrs.	Emp. Name	Date
	but/ours					Tillic		1119.	KIRIO WATERION			
	Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
								ity.	Do not require traceability.	Do not requ	Caps/Plugs	Caps/
						=	Lot Number.	wed by "	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
				I		box label.	date on the	mber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						etter "M."	ng with the l	el, startii	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Copper
				.		vord "heat."	above the w	l, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazin
A	7	A25	28			ox quantity.	bel under bo	he box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
3300	PEOR	A-RING					mbers	ablity Nu	Distinguishing Traceablity Numbers	Distingu		
AIA	7	1303-26-1/4	13	ļ					1		Order Qty	Orde
No(s)		Component(s)	Con		ררכ	devices, LLC	C C		394333	39	Order No.	Orde
Heat Lot/Traceability	Heat Lot	nonont(c))			ontrol	1		1303-26-1/4-25	1303-2	Part No.	Part