Test Form 11/4/15								ORD	BRAZING PRODUCTION RECORD	<b>BRAZING PR</b>
								6		
			D				4 FAIR 5 Training	(n. N		
	A STATE OF THE PARTY OF THE PAR	4	(c)	6	9th yes	1.26-16		- 11		
	Notes	Inspector	Rev Letter	Approved Mtrl Yes / No Check	Time Of Day Yes	Date Part Submitted		N to		
		t Inspection Record	First Part I			des	Down Time Codes	ctions	Special Notes / Instructions	Specia
	•									ROUTING:
	7									
	25									
	7/1									
	5									
				-						
				+	8					
	8				6	9	9	CAMIMON	200	1196/11
	Scrap	Notes		Code	Down Time Co	Cum. Iotal	otal Pcs.	Prod Hrs.	emp. Name	. / die
Scrap		AND THE RESIDENCE OF THE PARTY	Market Contact	Down Time		1000年 日本市场的 医子间 1000				
	Thru- put/8hrs		Pcs./Hr		Cycle Time	Setup Hrs.	- 10		Mach. No.	
				L			Do not require traceability.	Do not requ	Caps/Plugs	Cap
					-	Located on the bag followed by "Lot Number."	the bag followed	Located on	Snap Rings	Sna
		CP14			box label.	Use their work order number and date on the box label.	ork order numbe	Use their wo	Flare Tubes	Flan
		BRZ07			etter "M."	Located on the spool label, starting with the letter "M."	the spool label, s	Located on	Copper Tubing	Coppe
		CSW-3-5/8	0		ord "heat."	Located on the box label, directly above the word "heat."	the box label, dir	Located on	Brazing Rings	Brazi
		BRZ22			x quantity.	Six digit no. located on the box label under box quantity.	located on the b	Six digit no.	Flare Nuts	Flar
	- 1	CUTU-36-5/32	C			y Numbers	Distinguishing Traceablity Numbers	Distingu		
***	397730	SF5-2.5-16	S		1		2		Order Qty	Ord
	No(s)	Component(s)	6		devices, LLC	1	397730	39	Order No.	Orc
	Heat Lot/Traceability		,		2	1	S5-2.5-16-36-B	S5-2.5	Part No.	Pa