							ı			
							5 Training6 Meeting			
	HE	0	YES L	7:05	1-27-16					
Notes	Inspector	Mtrl Rev Letter	Approved N Yes / No Ch	Of Day	Date Part Submitted	lance				
	t Inspection Record	First Par				Down Time Codes			Special Notes / Instructions	Specia
			-			$\ \cdot\ $				ROUTING:
7 -	2.2									
10										
						+				
										100
	0	SOUT FO	2		ίζ		V	15	JU	1/25/11
	Notes	s	Down Time Code	Down Time	Cum. Total	-	Total Pcs	Prod Hrs.	Emp. Name	Date
put/8hrs	put,			Time	s.	Hrs.				
Thru-	HT.	Pcs./Hr		Cycle	dn	Setup			Mach. No.	
9						ability.	uire tracea	Do not require traceability.	Caps/Plugs	Caps
				• =	Located on the bag followed by "Lot Number."	ollowed by	the bag fo	ocated on		Snap
				e box label.	Use their work order number and date on the box label.	number a	ork order	Jse their w	Flare Tubes	Flare
		8		letter "M."	Located on the spool label, starting with the letter "M."	label, star	the spool	ocated on	m	Coppe
	CP13			word "heat."	Located on the box label, directly above the word "heat."	bel, direct	the box la	ocated on		Brazir
291906				ox quantity.	Six digit no. located on the box label under box quantity.	n the box	. located o	Six digit no	Flare Nuts	Flan
• ~	CUTU-1-1/2	5			lumbers	ceablity N	Distinguishing Traceablity Numbers	Disting		
ر	SF403-4-3/16	SF4	(4)			N	4		Order Qty	Ord
No(s)	component(s)	Com	LC	devices, LLC	4		396661	3,6	Order No.	Ord
Heat Lot/Traceability		,					5403-4-3/16	5403	Part No.	Pai