Test Form 11/4/15	Te									RD	BRAZING PRODUCTION RECORD	BRAZING PRO
									Training Meeting	6 5		
									FAIR			
	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling			
			rt Inspection Record	First Part In:					Down Time Codes		Special Notes / Instructions	Specia
												ROUTING:
	T.											
	ů,											
			T V.									
		U	7001									
		F	2									
		3										
				٥								
									100		SB	3/6
Scrap	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs. (Prod Hrs. To	Emp. Name	Date
		put/8hrs		Pcs./Hr			Time		Hrs.		Mach. No.	
		Thru-		•)	The state of the s		Cycle	ō	Setup			
									traceability.	Do not require traceability.	Caps/Plugs [Caps
						1		"Lot Number	Located on the bag followed by "Lot Number."	ocated on the	-	Snar
			ŭ)		L		e box label.	nd date on the	Use their work order number and date on the box label	Jse their work	Flare Tubes	Flare
							letter "M."	ting with the I	Located on the spool label, starting with the letter "M."	ocated on the	Copper Tubing	Coppe
							word "heat."	ly above the v	Located on the box label, directly above the word "heat."	ocated on the	Brazing Rings	Brazir
		4					ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	six digit no. loca	Flare Nuts	Flar
	20140766	3014	J-RING					umbers	Distinguishing Traceablity Numbers	Distinguishi		
	2	7	J3							100	Order Qty	Ord
	No(s)		Component(s)	Con			devices, LLC	T T	ຫ	399576	Order No.	Ord
	Heat Lot/Traceability	Heat Lot								J3-R	Part No.	Pa