			- v									
			<u> </u>									
	Notes	Inspector		o Check	Approved Yes / No	Time Of Day	Date Part Submitted	e	<ol> <li>Maintenance</li> <li>Tooling</li> <li>Setup</li> </ol>	V		
		Inspection Record	First Part I					e Codes	Down Time	ctions	Special Notes / Instructions	Specia
												ROUTING:
Z												
	-											
	Ą											
	3 101			+				$\dagger$				
1												
			. *									
									30		Sis	1/24
Scrap		Notes		ne	Down Time Code	Down Time	Cum. Total	5	Total Pcs.	Prod Hrs.	Emp. Name	Date
		The second second second second	No. of Participants	and Spinster,	STATE OF	ST. BANKS		o pedat culture		BOAL SAME	September September 1	
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
								ity.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
						`=	Lot Number	wed by "I	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Snap
						e box label.	date on the	mber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
				<u> </u>		letter "M."	ng with the	el, startir	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
					-	word "heat.	above the v	l, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazin
						ox quantity.	bel under b	he box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flare
	NA	G-RING					nbers	ablity Nur	Distinguishing Traceablity Numbers	Distingu		
	394787	702-10-3/16	70						20		Order Qty	Orde
	No(s)	component(s)	cor		LLC	devices, LLC	T		398164	39	Order No.	Orde
4	Heat Lot/ Traceability	amanatal al	2			200	ļ		105-TO-01 TO-1	T-701	. 140.	Part No.