							Meeting	6 (		
		7	1	13.7	1.10		FAIR	4. n		
		7	\	4	20.0	John John	Setup	З		
	Notes	Inspector	Mtrl Rev Letter	Approved N Yes / No CI	Time Of Day	Date Part Submitted	Maintenance Tooling	1 2		
		rt Inspection Record	First Part Ir				Down Time Codes	tions	Special Notes / Instructions	Speci
										ROUTING:
_										
								*		
+	15									
	3									
							ي	2 min	C	11/17
Scrap Scrap		Notes		Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hr		Cycle Time	s. up	Setup Hrs.		Mach. No.	
							Do not require traceability.	Do not requir		Cap
					=	'Lot Number	Located on the bag followed by "Lot Number."	Located on th		Sna
					box label.	nd date on the	Use their work order number and date on the box label.	Use their wor	Flare Tubes	Flan
					etter "M."	ting with the I	Located on the spool label, starting with the letter "M."	Located on th	Copper Tubing	Copp
					vord "heat."	tly above the v	Located on the box label, directly above the word "heat."	Located on th	Brazing Rings	Brazi
	4/2	BRZ00			ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	Six digit no. lo	Flare Nuts	Flai
	390611	CASC-13				lumbers	Distinguishing Traceablity Numbers	Distinguis		
	390611	ASC-13						2	Order Qty	Orc
	No(s)	component(s)	Con	LC	devices, LLC		611	390611	Order No.	Orc
<u> </u>	Heat Lot/Traceability	annout (c)	2		ontrol		13-9	ASC-13-9	Part No.	Pa