								Meeting	6 Me			
	1							5. ~ 5				
	Notes	Inspector		d Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	 Mainter Tooling 			
		First Part Inspection Record	First Part Ir					Down Time Codes	Do	uctions	Special Notes / Instructions	Specia
												ROUTING:
C												
P												
	U.	8										
	1	1										
								1				
+												
								_				
								-			SB	2/9
Scrap Scrap		Notes		ō	Down Time Code	Down Time	Cum. Total	Total Pcs.		Prod Hrs.	Emp. Name	Date
	put/8nrs					Time	·	nrs.				
	Thru-		Pcs./Hr			Cycle	- P	Setup		·	Mach. No.	
				9:				ceability.	Do not require traceability.	Do no	Caps/Plugs	Caps
							"Lot Number	Located on the bag followed by "Lot Number."	ed on the ba	Locate	Snap Rings	Snap
						e box label.	nd date on the	Use their work order number and date on the box label.	heir work or	Use th	Flare Tubes	Flare
						letter "M."	ting with the I	Located on the spool label, starting with the letter "M."	ed on the sp	Locate	Copper Tubing	Coppe
					9	vord "heat.'	ly above the v	Located on the box label, directly above the word "heat."	ed on the bo	Locate	Brazing Rings	Brazir
1	NA	G-RING				ox quantity.	label under bo	Six digit no. located on the box label under box quantity.	git no. locat	Six dig	Flare Nuts	Flan
	NA	G12					umbers	Distinguishing Traceablity Numbers	istinguishing	Di		
	397064	702-4-3/8	7						4		Order Qty	Ord
	No(s)	Component(s)	6		LLC	devices, LLC	T T		399881		Order No.	Ord
_	Heat Lot/Traceability					200		•	71-0/C-4-70/		rait No.	Par