										1		
									5 Training 6 Meeting			
									4 FAIR			
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	О	 Maintenance Tooling Setup 			
		t Inspection Record	First Part Ir					e Codes			Special Notes / Instructions	Specia
												ROUTING:
Z	`											
>	•											
	7 50											
	らんして											
	べる											
									Ŋ		SB	12/14
Scrap		Notes			Down Time Code	Down Time	Cum. Total	CL	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs		Pcs./Hr			Time		Hrs.			Mach. No.	
The parties of	Thru-				ALC: NO STANSON	Cycle	9	Setup				
				<u>. </u>				ity.	Do not require traceability.	Do not requ	Caps/Plugs	Cap
						=	Lot Number.	wed by "	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
						box label.	d date on the	mber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						etter "M."	ng with the l	el, starti	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
						vord "heat."	/ above the w	l, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
						ox quantity.	bel under bo	he box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
	9920h10e	J-RING					mbers	ablity Nu	Distinguishing Traceablity Numbers	Disting		
	2/2	501-4-1/4	5						5		Order Qty	Ord
-	No(s)	Component(s)	S S		ררכ	devices, LLC	H		393899	W.	Order No.	Ord
~	Heat Lot/Traceability					Ont no	ı		501-4-1/4-K	-TOC	ומונואט.	Pa