Test Form 11/4/15	Test									RD	BRAZING PRODUCTION RECORD	BRAZING PR
									Meeting			
									FAIR	4. 1		
									Setup	ω		
	Notes		Inspector	Rev Letter	Mtrl	Approved	Time Of Day	Date Part Submitted	Maintenance Tooling	1 2		
			First Part Inspection Record	First Part In				S	Down Time Codes	tions	Special Notes / Instructions	Specia
	Č											ROUTING:
	P											
	1.6			L								
	5.										1	
									100		56	1/22
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs		1 650/111			Time	Hrs.	-			
		Thru-		Pcs./Hr			Cycle	Setup	Se		Mach. No.	
									Do not require traceability.	Do not requir	Caps/Plugs	Сар
			£,		I			y "Lot Number	Located on the bag followed by "Lot Number."	Located on th		Sna
							e box label.	and date on the	Use their work order number and date on the box label.	Use their wo	Flare Tubes	Flan
							letter "M."	arting with the	Located on the spool label, starting with the letter "M."	Located on th	Copper Tubing	Copp
							word "heat."	ctly above the v	Located on the box label, directly above the word "heat."	Located on th	Brazing Rings	Brazi
							ox quantity.	x label under b	Six digit no. located on the box label under box quantity.	Six digit no. l	Flare Nuts	Flai
	NA	2	G-RING	5				Numbers	Distinguishing Traceablity Numbers	Distinguis		
	2 2	2.	G4						0	100	Order Qty	Orc
	No(s)	7	Component(s)	Cor		LLC	devices, LLC	Ţ	823	397823	Order No.	Orc
	Heat Lot/Traceability	Heat Lot							R	G4-R	Part No.	Pa