									6 Meeting			
										л Д с		
Notes	N	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Ф				
		rt Inspection Record	First Part Ir				HINE I	Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
Z												
>			-									
			<									
		20	7									
		1	5									
		5/1										
		7110										
+									C		E	(1/2)
scrap	-	Notes			Code	DOWII I IIIIe	Call. Total	2	Total res.	- 100	riip. Naille	) are
					Down Time	1	8 1		Total Day	District Control	E Nomo	7
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
A PARTY IN									The state of			
								ty.	Do not require traceability.	Do not requ	Caps/Plugs	Cap
						=	ot Number.'	wed by "L	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
						box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
						etter "M."	g with the le	el, startin	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
	-					ord "heat."	above the w	, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
1	2/4	G-RING				x quantity.	pel under bo	he box lab	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		G4	) ()				nbers	ablity Num	Distinguishing Traceablity Numbers	Distingu		
		702-12-3/16	70						10		Order Qty	Ord
	No(s)	-omponent(s)	Cor		TC	devices, LLC	7		400476	40	Order No.	Ord
eability	Heat Lot/Traceability	3505054(2)				2770			102-12-30 TO-4	T-701	2.0.	ra