Test Form 11/4/15	Test Forr										)RD	BRAZING PRODUCTION RECORD	BRAZING PRO
									Jq C	6 Meeting			
		*											
		- A. M. W. C. M. S. C	2		Cneck	Yes /, NO		פמסוווורובמ		3 Setup			
		Notes	Inspector	Rev Letter		Approved	Time Of Day	Date Part	nance				
			First Part Inspection Record	irst Part Ins	T				Down Time Codes	Down	ctions	Special Notes / Instructions	Specia
													ROUTING:
	1					ng							
							-   						
		is											
		10	136										
			5										
													1. ,
	_							0		6	10m10	42	11/HC
Scrap	Scrap	Sci	Notes			Down Time Code	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
1000		put/8nrs	0	2					1113.		Street and the second	とうなりません	
		Thru-		Pcs./Hr			Cycle	8	Setup			Mach. No.	
									ability.	uire trace	Do not require traceability.	Caps/Plugs	Caps
					1		=	Located on the bag followed by "Lot Number."	ollowed by	the bag f	Located or		Snap
							e box label.	Use their work order number and date on the box label.	number an	vork order	Use their v	Flare Tubes	Flare
							etter "M."	Located on the spool label, starting with the letter "M."	l label, starti	the spoo	Located or	Copper Tubing	Coppe
						e.	vord "heat."	Located on the box label, directly above the word "heat."	abel, directly	the box l	Located or	Brazing Rings	Brazir
							ox quantity.	Six digit no. located on the box label under box quantity.	on the box la	). located (	Six digit no	Flare Nuts	Flan
								imbers	Distinguishing Traceablity Numbers	uishing Tra	Disting		
			CUTU-1-1/2	CI						30		Order Qty	Ord
	s	No(s)	Component(s)	Com		ררכ	devices, LLC	F C		397473	3	Order No.	Ord
		Heat Lot/Traceability								CSW-1-1/2	(S)	Part No.	Par