Test Form 11/4/15	Те		THE REAL PROPERTY.						ORD	BRAZING PRODUCTION RECORD	BRAZING PR
		The state of the s			A CONTRACTOR OF THE PARTY OF TH		ad or	6 Meeting			
				Ó	9. 8	0176					
	Notes	Ven remail	Check	Yes / No	/J' 1 /	Submitted	7.0	<ul><li>2 Tooling</li><li>3 Setup</li></ul>			
	Net		Mtrl	Approved	Time Of Day	Date Part	nance	1 Maintenance			
		First Part Inspection Record	Firs				Down Time Codes	Down	ctions	Special Notes / Instructions	Specia
			Contract of the								ROUTING:
	7										
	(										
	627										
	7 / 6										
										173	
							210				
		<b>)</b>									
×											
	0					v		U	distance	1	1/4/1/16
COUR	k					J		s	3	1	17.
	Scrap	Notes		Down Time Code	Down Time	Cum. Total		Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8nrs				Time		nrs.				
	Thru-	Pcs./Hr	Po		Cycle	ָ ק <u>ק</u>	Setup			Mach. No.	
							ability.	uire tracea	Do not require traceability.	Caps/Plugs	Caps
						Located on the bag followed by "Lot Number."	ollowed by	the bag fo	Located or	Snap Rings	Snap
		L-RING			e box label.	Use their work order number and date on the box label	number a	vork order	Use their v	Flare Tubes	Flare
		12			letter "M."	Located on the spool label, starting with the letter "M."	l label, star	the spool	Located or	Copper Tubing	Coppe
		FLR-1/2		=	word "heat.'	Located on the box label, directly above the word "heat."	abel, direct	the box la	Located or	Brazing Rings	Brazir
		CFT-1/2			ox quantity.	Six digit no. located on the box label under box quantity.	on the box	. located c	Six digit no	Flare Nuts	Flan
	8	BRZ03				umbers	Distinguishing Traceablity Numbers	uishing Tra	Disting		
	797729	SF401-2-3/16						3		Order Qty	Ord
	No(s)	Component(s)		LLC	devices, LLC			397729	3	Order No.	Ord
22	Heat Lot/Traceability	?			7	ı		F401-2-3/16-2	F401	Part No.	Par