Test Form 11/4/15	Test F										ORD	BRAZING PRODUCTION RECORD	BRAZING PRO
	-									6 Meeting			
										3 Setup			
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Ce	 Maintenance Tooling 			
			Inspection Record	First Part In					e Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	1												
	3												
		(F)											
											1		
										OE	2	SB	81/1
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	C	Total Pcs.	Prod Hrs.	Emp. Name	Date
		Thru- put/8hrs		Pcs./Hr			Cycle	- 3	Hrs.			Mach. No.	
				Parameter Spale Service	processor and the second	The second second	The state of the s	STATE OF STREET	A DOMESTIC	A STATE OF THE STATE OF	STREET, STREET		
									lity.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
					I		ੱਛ	Located on the bag followed by "Lot Number."	owed by	the bag follo	Located on	Snap Rings	Snap
					I.		box label.	Use their work order number and date on the box label	ımber an	ork order nu	Use their w	Flare Tubes	Flare
					<u> </u>		etter "M."	Located on the spool label, starting with the letter "M."	bel, starti	the spool la	Located on	Copper Tubing	Coppe
						9	vord "heat."	Located on the box label, directly above the word "heat."	el, directi	the box labe	Located on	Brazing Rings	Brazir
							ox quantity.	Six digit no. located on the box label under box quantity.	the box la	located on	Six digit no.	Flare Nuts	Flare
		30140766	J-RING					mbers	ablity Nu	Distinguishing Traceablity Numbers	Distingu		
		NIA	501-6-3/16	50						20		Order Qty	Orde
		No(s)	component(s)	Con		LLC	devices, LLC	THE STATE OF THE S		397223	39	Order No.	Orde
	ility	Heat Lot/Traceability					2	ı		501-6-3/16-R	501-6	Part No.	Par