Test Form 11/4/15	Te										ORD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
										4 FAIR			
	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	се	 Maintenance Tooling 			
			Inspection Record	First Part I					ne Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	T												
	>												
			(
			S										
			7.000.		-								
		+	200										
		0											
										S		50	26/25
Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	5	Total Pcs.	Prod Hrs.	Emp. Name	Date
	THE PARTY OF THE P	· 日本市場本の企用では	1000年の大学は	The Part of the Pa									
		Thru- put/8hrs		Pcs./Hr			Cycle Time	J	Setup Hrs.			Mach. No.	
									lity.	Do not require traceability.	Do not req	Caps/Plugs	Caps
							=	Located on the bag followed by "Lot Number."	owed by "	the bag follo	Located on	Snap Rings	Snap
					1		box label.	Use their work order number and date on the box label.	ımber and	ork order nu	Use their w	Flare Tubes	Flare
							etter "M."	Located on the spool label, starting with the letter "M."	bel, starti	the spool lal	Located on	Copper Tubing	Coppe
							vord "heat."	Located on the box label, directly above the word "heat."	el, directly	the box labe	Located on	Brazing Rings	Brazir
	AS	NIA	J2-1/2		I		x quantity.	Six digit no. located on the box label under box quantity.	the box la	. located on t	Six digit no	Flare Nuts	Flan
	3766	991040766	J-RING				9	mbers	ablity Nu	Distinguishing Traceablity Numbers	Disting		
	A	NIA	502-7-3/16	5(•					5		Order Qty	Ord
	No(s)	No	component(s)	ć		LLC	devices, LLC	4		401837	40	Order No.	Ord
	Heat Lot/Traceability	Heat Lot/T	nnonon+(c)				ontrol	1		502-7-3/16-2.5	502-7	Part No.	Par