										0.2.55	6		ŭ.
							s				4.7		
											(n)		
	Š	Notes	Inspector	Rev Letter	Mtrl	Approved Yes / No	Time Of Day	Date Part Submitted		<ul><li>Maintenance</li><li>Tooling</li></ul>	2		
			First Part Inspection Record	First Part I					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
	,												ROUTING:
	8												
												1	
		(								# P			
		30										,	
		J.											
							I I						
										-			, ,
	$\beta$									24	がごろ	YU	11/13/15
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
		barl out					Tilling		1113.				
		Thru-		Pcs./Hr			Cycle		Setup			Mach. No.	
										Do not require traceability.	Jo not requ	Caps/Plugs	Caps
								ot Number.	ed by "Lo	Located on the bag followed by "Lot Number."	ocated on t		Snap
							box label.	date on the	ber and o	Use their work order number and date on the box label.	Jse their wo	Flare Tubes	Flare
					•		tter "M."	with the le	l, starting	Located on the spool label, starting with the letter "M."	ocated on t	σα	Coppe
							ord "heat."	bove the w	directly a	Located on the box label, directly above the word "heat."	ocated on t	Brazing Rings	Brazin
		NIA	BRZ00				x quantity.	el under bo	box lab	Six digit no. located on the box label under box quantity.	six digit no. I	Flare Nuts	Flare
		N/A	CASC-13					bers	lity Num	Distinguishing Traceablity Numbers	Distingui		
		NIA	ASC-13	9	•					48	2	Order Qty	Orde
		No(s)	ipolicii (a)	0		LC	devices, LLC	d d		390239	390	Order No.	Orde
	oility	Heat Lot/Traceability	Component(s)	Con			ontrol	J	•	ASC-13-9	ASC	No.	Part No.