Test Form 11/4/15	Test										)RD	BRAZING PRODUCTION RECORD	BRAZING PR
										6 Meeting			
	(#E)	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	(D)	<ol> <li>Maintenance</li> <li>Tooling</li> </ol>			
			First Part Inspection Record	First Part Ir					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
													ROUTING:
												€2	
										+		SB	3/6
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Cu Cu	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs		F65./ FII			Time		Hrs.			INIGCII. INO.	
	obsession and a	Thru-		Dec /Hr			Cycle		Setup			Mach No	
									ty.	Do not require traceability.	Do not requ	Caps/Plugs	Сар
							° =	Lot Number.	ved by "I	Located on the bag followed by "Lot Number."	Located on	Snap Rings	Sna
					I		box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flare
					1		etter "M."	ng with the l	el, startir	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Coppe
					I		vord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Brazi
		N/A	E15		ı		ox quantity.	bel under bo	ne box lal	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Flar
		20060667	E-RING					nbers	blity Nur	Distinguishing Traceablity Numbers	Distingu		
		398954	901-12-3/16	90						4		Order Qty	Ord
		No(s)	Component(s)	Co.		LLC	devices, LLC	H		399575	39	Order No.	Ord
	ility	Heat Lot/Traceability		)			7			901-12-3/16-15	901-12	Part No.	Pa