									6 Meeting			
	No. Helicaster			Check	Yes / No		Submitted		2 Tooling3 Setup			
	Notes	Inspector	Rev Letter	Mtrl	Approved	Time Of Day	Date Part					
		rt Inspection Record	First Part I					Codes	Down Time Codes	tions	Special Notes / Instructions	Specia
												ROUTING:
	*											
\												
1												
Gar	12											
0												
		5.0										
			7									
									_		SB	1-13
rap Scrap Code	Scrap	Notes			Down Time Code	Down Time	Cum. Total	Cu	Total Pcs.	Prod Hrs.	Emp. Name	Date
	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
												- Color of Color
								Υ.	Do not require traceability.	Do not requ		Cap
						я	ot Number.	ved by "L	Located on the bag followed by "Lot Number."	ocated on	Snap Rings	Snaj
						box label.	date on the	nber and	Use their work order number and date on the box label.	Jse their w		Flare
						etter "M."	ng with the le	el, startin	Located on the spool label, starting with the letter "M."	ocated on	Copper Tubing	Coppe
						ord "heat."	above the w	directly	Located on the box label, directly above the word "heat."	ocated on	Brazing Rings	Brazii
						x quantity.	oel under bo	e box lat	Six digit no. located on the box label under box quantity.	six digit no.	Flare Nuts	Flar
	Z. A	C-RING					nbers	blity Nun	Distinguishing Traceablity Numbers	Distingu		
	N.A	1102-11-5/16	110						1		Order Qty	Ord
	No(s)	component(s)	Con		LLC	devices, LLC	H		396774	39	Order No.	Ord
	Heat Lot/Traceability	1	2			Opt pol			1102-11-5/16-R	1102-1	Part No.	Pai