Test Form 11/4/15	Test F									ORD	BRAZING PRODUCTION RECORD	BRAZING PRO
										6		
			-						I FAIR Training	4.7		
										3		
		Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	2		
			rt Inspection Record	First Part In				S	Down Time Codes	tions	Special Notes / Instructions	Specia
							٠					ROUTING:
	9											
	?											
		). \	to									
		5.	12.4									
			7									
				1					<i>ao</i>		36	12/2
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs.	Prod Hrs.	Emp. Name	Date
		put/8hrs					lime	HIS.				
		Thru-		Pcs./Hr			Cycle	Setup	Se		Mach. No.	
	L								Do not require-traceability.	Do not requi	Caps/Plugs	caps
							=	y "Lot Number.	Located on the bag followed by "Lot Number."	Located on t		Snap
				1			box label.	and date on the	Use their work order number and date on the box label.	Use their wo		Flare
ů.							etter "M."	rting with the l	Located on the spool label, starting with the letter "M."	Located on t	90	Coppe
							vord "heat."	tly above the w	Located on the box label, directly above the word "heat."	Located on t	Brazing Rings	Brazir
							ox quantity.	( label under bc	Six digit no. located on the box label under box quantity.	Six digit no. l	Flare Nuts	Flan
		H0515106	G-RING					Numbers	Distinguishing Traceablity Numbers	Distingui		
		390422	702-10-3/16	702					20	2	Order Qty	Orde
		No(s)	Lomponent(s)	Con		LLC	devices, LLC		392268	392	Order No.	Ord
	ity	Heat Lot/Traceability		,			7		702-10-3/16-R	702-10	Part No.	Par