											BBAZING BBODI CTION BECORD	DATINIC DD
								ting	6 Meeting			
								2. T				
8	Notes	Inspector		d Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling Setun	1 Mainter 2 Tooling			
		First Part Inspection Record	First Part I					Down Time Codes	Dov	ctions	Special Notes / Instructions	Specia
												ROUTING:
Q	115											
	1.15.											
	1		tz									
5								+			1	
				\dagger				+				
								0	ose		38	1-13
Scrap Scrap Code		Notes		те <u> </u>	Down Time Code	Down Time	Cum. Total	Total Pcs.		Prod Hrs.	Emp. Name	Date
	put/8hrs					Time	•	Hrs.				
	Thru-		Pcs./Hr			Cycle	ō	Setup		Activities and	Mach. No.	
				L				ceability.	quire tra	Do not require traceability.	Caps/Plugs	Caps
						• =	"Lot Number	Located on the bag followed by "Lot Number."	on the ba	Located c	Snap Rings	Snap
				**************************************		e box label.	id date on the	Use their work order number and date on the box label.	work ord	Use their	Flare Tubes	Flare
						letter "M."	ing with the l	Located on the spool label, starting with the letter "M."	on the spo	Located c	Copper Tubing	Coppe
					-	word "heat.'	y above the v	Located on the box label, directly above the word "heat."	on the bo	Located c	Brazing Rings	Brazin
						ox quantity.	abel under bo	Six digit no. located on the box label under box quantity.	າo. locate	Six digit n	Flare Nuts	Flare
	NIM	G-RING					_u mbers	Distinguishing Traceablity Numbers	guishing	Distin		
	393842	702-8-3/16	7(20		Order Qty	Orde
	No(s)	omponent(s)			ררכ	devices, LLC	±		396779		Order No.	Orde
ility	Heat Lot/Traceability	ppopp+(c)	2				J	R	702-8-3/16-R	702	Part No.	Par