								Meeting			
			ļ					FAIR Training			
			-					-b			
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Maintenance Tooling	1 Ma 2 Too		
		First Part Inspection Record	First Part					Down Time Codes		Special Notes / Instructions	Special N
											ROUTING:
1											
		1									
	(3)	فر							-		
	CAS										
									1		
								9		ć	9
								7		A P	3/20
Scrap Scrap		Notes			Down Time Code	Down Time	Cum. Total	Total Pcs. Cu	Prod Hrs. Tot	Emp. Name P	Date
	put/8hrs		18 100000			Time		Hrs.			
	Thru-		Pcs./Hr			Cycle		Setup		Mach. No.	
				_				aceability.	Do not require traceability.	×	Caps/Plugs
						=	ot Number.	Located on the bag followed by "Lot Number."	cated on the b		Snap Rings
				<b>!</b>		box label.	date on the	Use their work order number and date on the box label.	e their work or	_	Flare Tubes
	*					etter "M."	ng with the I	Located on the spool label, starting with the letter "M."	cated on the sp	T	Copper Tubing
						ord "heat."	above the w	Located on the box label, directly above the word "heat."	cated on the b		<b>Brazing Rings</b>
						x quantity.	bel under bo	Six digit no. located on the box label under box quantity.	digit no. locat		Flare Nuts
		G-RING	i d				nbers	Distinguishing Traceablity Numbers	Distinguishin		
	405660	GR4							405659	Qty	Order Qty
	No(s)	Component(s)	6		LLC	devices, LLC	4		405659	No.	Order No.
	Heat Lot/Traceability		,			1			GK4-K	NO.	Part No.