Test Form 11/4/15	Tes										ORD	<b>BRAZING PRODUCTION RECORD</b>	BRAZING PR
										6 Meeting			
	Notes		Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	Ge Ce	<ol> <li>Maintenance</li> <li>Tooling</li> </ol>			
			Inspection Record	First Part Ir					e Codes	Down Time Codes	ctions	Special Notes / Instructions	Specia
													ROUTING:
	Ø												
\	) Ž	+											
	2												
	3												
	5												
	,												
										دو		SB	12/30
Scrap Code	Scrap		Notes			Down Time Code	Down Time	Cum. Total	C	Total Pcs.	Prod Hrs.	Emp. Name	Date
		Thru- put/8hrs		Pcs./Hr			Cycle Time	ъ	Setup Hrs.			Mach. No.	
		To the second second	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN THE PERSON NAMED IN COLUMN TWO IS NAMED IN THE PERSON NAMED IN THE PERSON NAMED IN THE PERSON N	The state of the s	<b>美国联络科技</b>	Water Control of the last	Spirit of the second	在 一		日の大学を持ちるとはなるとの	STATE OF THE PARTY	Sept. Sept. Sept. Sept.	
									ity.	Do not require traceability.	Do not requ	Caps/Plugs	Caps
							-	Located on the bag followed by "Lot Number."	wed by '	the bag follo	Located on	Snap Rings	Snap
					I		box label.	Use their work order number and date on the box label.	mber an	ork order nu	Use their w	Flare Tubes	Flare
					I		etter "M."	Located on the spool label, starting with the letter "M."	el, starti	the spool lak	Located on	Copper Tubing	Coppe
						10	vord "heat."	Located on the box label, directly above the word "heat."	l, directly	the box labe	Located on	Brazing Rings	Brazir
	2/2	7	A-KF004	1			ox quantity.	Six digit no. located on the box label under box quantity.	he box la	located on t	Six digit no.	Flare Nuts	Flare
	ZX		DCN316-HT	DC				mbers	ablity Nu	Distinguishing Traceablity Numbers	Distingu		
	95020	بون	2203A-5-1/4-0	220.						2		Order Qty	Orde
	No(s)		component(s)	Con		LLC	devices, LLC	C C		395433	39	Order No.	Ord
	Heat Lot/Traceability	Heat Lo	nonon+(c)	Car			ontrol	1		2203A-5-1/4	2203	Part No.	Par