									4 FAIR 5 Training			
	Notes	Inspector	Rev Letter	Mtrl Check	Approved Yes / No	Time Of Day	Date Part Submitted	nce				
		Part Inspection Record	First Part In					Down Time Codes			Special Notes / Instructions	Special
												ROUTING:
D												
)		1										
		(										
		7										
		2000			**							
		0 210										
	0		ı									
									50		SB	3/35
Scrap		Notes			Down Time Code	Down Time	Cum. Total	10	Total Pcs.	Prod Hrs.	Emp. Name	Date
A SQ Brownia	Thru- put/8hrs		Pcs./Hr			Cycle Time		Setup Hrs.			Mach. No.	
								ollity.	Do not require traceability.	Do not requ	cdps/Flugs	caps
							ot Number.	Located on the bag followed by "Lot Number."	the bag fol	Located on		Snap
						box label.	date on the	Use their work order number and date on the box label	ork order n	Use their w	Flare Tubes	Flare
,						etter "M."	g with the le	Located on the spool label, starting with the letter "M."	the spool la	Located on	Copper Tubing	Coppe
						ord "heat."	above the w	Located on the box label, directly above the word "heat."	the box lab	Located on	Brazing Rings	Brazin
1				l		x quantity.	el under bo	Six digit no. located on the box label under box quantity.	. located on	Six digit no	Flare Nuts	Flare
	ZX	G-RING					bers	Distinguishing Traceablity Numbers	uishing Trac	Disting		
	401601	702-8-1/4	71				-11		50		Order Qty	Orde
	No(s)	Component(s)	Con		LLC	devices, LLC	H		401856	40	Order No.	Orde
4	Heat Lot/Traceability		)			200			/02-8-1/4-R	/02-	Part No.	Par