		THE RESIDENCE OF THE PARTY OF T			NECTORISM	-			Meeting	6 (
		the state of the s	1		XEZ	18:45	5-8-16	1		U 4. n		
	Notes	Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted	No.		2 2 1	545	
	The second second second	rt Inspection Record	First Part In	A		Control of the last		Codes			Special Notes / Instructions	Speci
Y												ROUTING:
7												
P												
	70											
	P	3										
	7	1										
		10										
	>											
						3						
										3		. 3
							6	à	0 JO	TO TOWN	Y	1/0/16
Scrap		Notes		n.	Down Time Code	Down Time	Cum. Total	Cum	Total Pcs.	Prod Hrs.	Emp. Name	Date
2	put/8hrs 192	24	Pcs./Hr	MIN	2	Time	20 MIN	Hrs.	2		Mach. No.	
	The state of the s		A COLUMN TO SERVICE AND A SERV	Mary Carlotte	100 miles	Cools	SOFT SECTION SORES	Cotun		A PROPERTY OF	A STATE OF THE PARTY OF THE PAR	
									Do not require traceability.	o not requ	Caps/Plugs [Сар
						=	ot Number.	ed by "Lo	Located on the bag followed by "Lot Number."	ocated on t	Snap Rings	Sna
		CP13				box label.	date on the	ber and c	Use their work order number and date on the box label	Jse their wo	Flare Tubes	Flan
		BRZ25				etter "M."	with the le	, starting	Located on the spool label, starting with the letter "M."	ocated on t	Copper Tubing	Coppe
		BRZ01				ord "heat."	bove the w	directly a	Located on the box label, directly above the word "heat."	ocated on t	Brazing Rings	Brazi
		CUTU-14-1/4	CUT			x quantity.	el under bo	box labe	Six digit no. located on the box label under box quantity.	ix digit no.	Flare Nuts	Flar
		CUTU-3-1/2	CU				bers	lity Num	Distinguishing Traceablity Numbers	Distingu		
		SF4-4-5	"						20		Order Qty	Ord
	No(s)	component(s)	Coll		LLC	devices, LLC	4		403427	40:	Order No.	Ord
₹	Heat Lot/Traceability	non+(c)	2			0000			54-4-5-14	34	Part No.	Pa