									6 Meeting			
	Notes	Inspector	Rev Letter	Check	Yes / No	Time Of Day	Submitted	30	2 Tooling 3 Setup			
		rt Inspection Record	First Part In	201	200		Data	Codes	Down Time Codes	tions	Special Notes / Instructions	Spec
												KOO IING:
7	<u></u>											
	*>											
L	500	7										
	び	7										
		2										
_												
											>	
\downarrow												21.5
Scrap	Sci	Notes			Down Time Code	Down Time	Cum. Total	Cu	Total Pcs.	Prod Hrs.	Emp. Name	Date
	put/8hrs					Time		Hrs.				
	Thru-		Pcs./Hr			Cycle	_	Setup			Mach. No.	
								Į į	Do not require traceability.	Do not requ	Caps/Flugs	car
•				1		=	Lot Number.	ved by "	Located on the bag followed by "Lot Number."	Located on		Sna
						box label.	date on the	nber and	Use their work order number and date on the box label.	Use their w	Flare Tubes	Flar
						etter "M."	ng with the I	el, startii	Located on the spool label, starting with the letter "M."	Located on	Copper Tubing	Copp
			ě.		-	vord "heat."	above the v	, directly	Located on the box label, directly above the word "heat."	Located on	Brazing Rings	Braz
						ox quantity.	bel under bo	ne box la	Six digit no. located on the box label under box quantity.	Six digit no.	Flare Nuts	Fla
	(modo000	E-RING					mbers	blity Nu	Distinguishing Traceablity Numbers	Distingu		
-	こチ	E6							10		Order Qty	Or
	No(s)	Component(s)	CON		LLC	devices.	H		400389	40	Order No.	Or
	Heat Lot/Traceability)			7			E6-R	m	Part No.	Pa